

FOTECHEM Stencil Chemicals

make you forget all others

The **key** to successful stencil making is the correct
MESH PREPARATION



1 DEGREASER

solutions to remove dirt, dust and greasy residues from all fabrics.

First step before coating emulsions on new or used fabric:

2003 practical, ready-to-use gel

2033 economic concentrate
(mix 10 parts water to 1 part 2033)

2033S low foam concentrate; for machine use
(mix up to 1 : 100)

2 ABRASIVE DEGREASER

gel that combines 2 actions in one step:

First step before adhering capillary or indirect films or coating new fabric:

2023 thick gel that promotes better wetting of the fabric
and improves the adhesion of the stencil for longer press life

3 MESH PREPARATION

promotes fabric water retention.

The step before adhering capillary films on all mesh:

2025 ready-to-use gel

Helpful for uniform adhesion of FOTECAP capillary films

4 FLOW SUPPORT & DEGREASER

Improved mesh pre-treatment and simultaneous degreasing

The step to assist the flow of coated emulsion on new or used fabrics

2002 gel, can be applied by coating trough

2022 economic concentrate
(mix 10 parts water to 1 part 2022)



BE SAFE - USE FOTECHEM

fully compatible with all FOTECO stencil systems

FOTEC AG, P.O.Box 1123, Eigenheimstr. 22, CH-8700 Küsnacht, Switzerland
TEL. +41 44 913 30 00 FAX +41 44 910 45 25 info@fotec.ch www.fotec.ch