

# FOTECHEM Stencil Chemicals

make you forget all others

The **key** to successful stencil making is the correct  
**DECOATING** and **HAZE REMOVAL**



## 1 REMOVERS / DECOATERS

solutions for fast and thorough decoating of emulsions and capillary films for all meshes.

*First step after ink removal and screen wash:*

### 2004 ready-to-use liquid

*deep penetration, odour free*

### 2005 ready-to-use paste

*easier and more speedy handling for large sizes*

### 2044 remover powder in sachets

*to be dissolved in water, 100 gr make 10-20 ltr. solution*

### 2040 economic concentrated liquid

*for machine decoating; 1 part 2040 to 20 parts water*

### 2042 economic concentrated liquid

*for machine decoating; 1 part 2042 to 30 parts water*

*To speed up stencil removal:*

**degrease first** after cleaning the ink and before applying the remover !

## 2 INK HAZE and STENCIL RESIDUES

removers for all stencil systems and on all meshes.

*A step that is needed for a cleaner mesh:*

### 2080 high alkaline paste

*for cleaning and degreasing;  
should be used together with 2085*

### 2085 alkaline liquid regenerator

*solution with emulsifying effect; pleasant odour*

### 2088 ghost picture removal

*one component gel; mild reaction*

### 2089 ghost & diazo stain remover

*one component alkaline gel containing cleaning solvents; direct application with brush or coating trough*



## BE SAFE - USE FOTECHEM

*fully compatible with all FOTECO systems*

FOTEC AG, P.O.Box 1123, Eigenheimstr. 22, CH-8700 Küsnacht, Switzerland  
TEL. +41 44 913 30 00 FAX +41 44 910 45 25 [info@fotec.ch](mailto:info@fotec.ch) [www.fotec.ch](http://www.fotec.ch)